


Service
Service
Service

Service Manual

For record changer see 22GC051/R version



Safety regulations require that the set be restored to its original condition and that parts which are identical with those specified, be used.


Documentation Technique Service Dokumentation Documentazione di Servizio Huolto-Ohje Manual de Servicio Manual de Servicio








Subject to modification
4822 726 11776
Printed in The Netherlands






PHILIPS

CS56448



 $\frac{1}{8}W \pm 5\%$
 $\frac{1}{2}W \pm 5\%$
 PLATE CERAMIC
 FLAT-FOIL POLYESTER CAPACITOR
 ELECTROLYTIC CAPACITOR

10574C12

-TS-IC- 			-R- 			-SK- 		
IC419 TS421 TS422	TBA641B12 AC187 BC548B	4822 209 80271 5322 130 40314 4822 130 40937	R428 R429 R431 R432 R511 R514	100 Ω (lin) 2k2 (lin) 220k (log) 100k (spez) 680 Ω - 0,4W±2% 1k2 - 0,4W ± 2%	4822 100 10075 4822 100 10029 4822 105 10287 4822 105 10286 5322 116 54534 5322 116 54557	SK3	4822 272 10083	
-D- 			-L-S- 			-Miscellaneous-		
D406 D423,424	BAX18 BY206	5322 130 34121 4822 130 30839	L426 S403	4 Ω	4822 157 50789 4822 240 10021	T408 F1 M	4822 145 40147 4822 252 20007 4822 361 20112	

	712	701	718 702 708=710 704 707 703	715 713 705 706 711		
C					432	518
R	431 516 509=512 514 428 429 501 515 513	517	502 503 504	505		SK3 T408 F1
MISC	SK1 D423 424	SK 2	L 426 BU1 TS422 421	BU 2 IC 419 M	D406	




Fig. 2




Fig. 3

10699E12